

Corvette

	09/10/05				05/12/06				06/24/06				08/26/06			
	1	2	3	4	1	2	1	2	3	1	2	3	4	5	1	2
RT	0.507	0.274	0.105	0.465	0.178	0.147	0.155	0.179	0.476	0.227	-0.023	0.228	0.376	-0.224	0.124	0.403
60	3.005	2.632	2.994	2.570	3.002	2.706	2.685	2.796	2.619	2.537	2.447	2.461	2.453	2.595	2.473	2.443
330	7.673	7.149	7.532	6.906	7.731	7.290	7.108	7.117	6.863	6.944	6.686	6.764	6.726	7.055	6.706	6.735
1/8 mile	11.275	10.792	11.073	10.400	11.299	10.884	10.639	10.612	10.300	71.790	10.122	10.184	10.141	10.535	10.105	10.171
1000	14.308	13.905	14.079	13.385	14.342	13.940	13.623	13.577	13.225	13.341	13.051	13.096	13.048	13.482	13.004	13.096
1/4 mile	16.874	16.516	16.595	15.923	16.912	16.506	16.126	16.071	15.686	15.815	15.520	15.622	15.648	15.965	15.444	15.556
60	3.005	2.632	2.994	2.570	3.002	2.706	2.685	2.796	2.619	2.537	2.447	2.461	2.453	2.595	2.473	2.443
60-330	4.668	4.517	4.538	4.336	4.729	4.584	4.423	4.321	4.244	4.407	4.239	4.303	4.273	4.460	4.233	4.292
330-1/8	3.602	3.643	3.541	3.494	3.568	3.594	3.531	3.495	3.437	64.846	3.436	3.420	3.415	3.480	3.399	3.436
1/8-1000	3.033	3.113	3.006	2.985	3.043	3.056	2.984	2.965	2.925	-58.449	2.929	2.912	2.907	2.947	2.899	2.925
1000-1/4	2.566	2.611	2.516	2.538	2.570	2.566	2.503	2.494	2.461	2.474	2.469	2.526	2.600	2.483	2.440	2.460
Launch	Bog	Bog	Bog	Spun good	Low	Spun OK	Slip clutch	Slip clutch	Spun	Spun	Spun	Spun	Spun	Not good spin	Tons of spin	Lots of spin
Shift point	Redline	Redline	5000	Redline	Redline	5000	Redline until 4 th	Redline	Redline	Ran all way to 6500 rpm	Ran all way to 6500 rpm	Ran all way to 6500 rpm	Ran all way to 6500 rpm	Ran all way to 6500 rpm	Ran all way to 6500 rpm	Ran all way to 6500 rpm
				Stopped			Hot engine	Pulled strong	Pulled strong			Braked	Braked		Very cooled off engine	Very cooled off engine

Mustang

	06/10/2006 (1 st Engine)				07/20/2007 (2 nd Engine)				08/27/07				09/07/07				04/13/08				
	1	2	3	4	1	2	3	4	5	1	2	3	1	2	3	4	1	2	3	4	5
RT	0.493	0.194	0.204	1.920	0.116	0.343	0.088	0.017	0.338	0.001	0.008	0.286	0.090	0.006	0.100	0.124	0.459	0.312	0.174	-0.139	0.060
60	3.341	2.325	2.428	2.525	2.306	2.483	2.403	2.359	2.527	2.347	2.386	2.346	2.163	2.213	2.206	2.225	3.632	2.751	2.373	2.334	2.125
330	8.155	6.600	6.667	6.752	6.478	6.745	6.697	6.648	6.958	6.694	6.769	6.696	6.106	6.143	6.167	6.181	8.371	6.839	6.236	6.208	5.973
1/8 mile	11.917	10.263	10.040	10.127	10.221	10.271	10.235	10.174	10.865	10.295	10.332	10.264	9.335	9.358	9.424	9.414	11.775	10.070	9.418	9.400	9.166
1000	15.118	13.375	12.928	13.017	13.504	13.304	13.290	13.214	14.114	13.401	13.389	13.346	12.108	12.120	12.230	12.188	14.645	12.850	12.180	12.162	11.931
1/4 mile	17.778	15.950	15.365	15.465	16.208	15.870	15.976	15.790	16.801	16.009	15.974	15.959	14.458	14.463	14.605	14.539	17.050	15.214	14.539	14.519	14.290
MPH										86.970	87.460	86.480	96.250	96.420	95.160	96.090	94.250	95.450	95.830	95.700	95.700
60	3.341	2.325	2.428	2.525	2.306	2.483	2.403	2.359	2.527	2.347	2.386	2.346	2.163	2.213	2.206	2.225	3.632	2.751	2.373	2.334	2.125
60-330	4.814	4.275	4.239	4.227	4.172	4.262	4.294	4.289	4.431	4.347	4.383	4.350	3.943	3.930	3.961	3.956	4.739	4.088	3.863	3.874	3.848
330-1/8	3.762	3.663	3.373	3.375	3.743	3.526	3.538	3.526	3.907	3.601	3.563	3.568	3.229	3.215	3.257	3.233	3.404	3.231	3.182	3.192	3.193
1/8-1000	3.201	3.112	2.888	2.890	3.283	3.033	3.055	3.040	3.249	3.106	3.057	3.082	2.773	2.762	2.806	2.774	2.870	2.780	2.762	2.762	2.765
1000-1/4	2.660	2.575	2.437	2.448	2.704	2.566	2.686	2.576	2.687	2.608	2.585	2.613	2.350	2.343	2.375	2.351	2.405	2.364	2.359	2.357	2.359
Launch	Hesitate	Some Spin	Big Spin	Big Spin	2000	2250	2000	2000	2250								2000	1750	2000	2000	2200
Shift point	Manual shift	Auto Shift	Manual shift	Manual shift	5300, auto to 3rd (5000)	5300, auto to 3rd (5000)	5300, auto to 3rd (5000)	5300, auto to 3rd (5000)	Spinning caused problems								6000	6000	6000	6000	6000
																		Can't launch, just spinning through all gears			Let more air out of times, much better
	Engine way to hot				Engine way to hot	Spin, spin, spin	Braked at end		Spin, spin, spin								Way cold, spinning like on ice	Regular tires	Little better, still spinning	Little better, still spinning	slight spin, much better
	First runs, Tranny linkage and shifter all messed up						Regular tires, to about 20 pounds 2 nd gear all screwed up!!!						Drag radials 20LBS	Drag radials 20LBS	Drag radials 20LBS	Drag radials 20LBS		Drag radials 20LBS	Drag radials 20LBS	Drag radials 20LBS	Drag radials 15LBS